

UNIVERSITY OF MONTANA-WESTERN
 ADA SELF EVALUATION
 2005

FACILITY: Block Hall Page 1 of 2

| Location | Barrier | Long Term Solution | Interim Step | Cost | Schedule/Priority |
|--|--|---|----------------------------------|-------------|--------------------------|
| Women's 1 st Floor Restroom | No covers on pipes under sink | Install protective covers under sink | No interim step | \$110 | Medium |
| Women's 1 st Floor Restroom | Doors have clearance of 34" | Replace with at least 36" clearance doors | No interim step | | Medium |
| Men's 1 st Floor Restroom | No covers on pipes under sink | Install protective covers under sink | No interim step | \$110 | Medium |
| Hallway doors on both ends | Standard door knobs | Provide levers | No interim step | \$1,000 | High |
| 1 st Floor Drinking Fountains | Drinking fountains not accessible | Lower and activate | In interim step | \$800 | High |
| 2 nd Floor Entry Doors | Standard door knobs | Provide levers | No interim step | \$1,000 | |
| Room 203 | No specific handicap seating at tables | Designate spaces for handicap seating | Sit in front or at end of tables | | |
| 3 rd Floor Entry Doors | Standard door knobs | Provide levers | No interim step | \$1,000 | High |
| Room 309 | No specific handicap seating | Designate spaces for handicap seating | Sit in front | | Low |

| | | | | | |
|----------|------------------------------|------------------------------|--------------|--|-----|
| Room 303 | No specific handicap seating | Designate spaces for seating | Sit in front | | Low |
|----------|------------------------------|------------------------------|--------------|--|-----|

| | | | | | |
|--|--|--|--|--|--|
| | | | | | |
|--|--|--|--|--|--|

UNIVERSITY OF MONTANA-WESTERN
 ADA SELF EVALUATION
 2005

FACILITY: Main Hall Page 1 of 1

| <i>Location</i> | <i>Barrier</i> | <i>Long Term Solution</i> | <i>Interim Step</i> | <i>Cost</i> | <i>Schedule/Priority</i> |
|------------------------|-------------------------------------|----------------------------------|-----------------------------|--------------------|---------------------------------|
| Room 301 | Not accessible by handicapped | Add elevator | Move to different classroom | \$19,592 | Low |
| Room 402 | Not accessible by handicapped | Lift needed | 4 steps | \$19,793 | Medium |
| Room 415 | Not accessible by handicapped | Install 67 ½" lift | Move to different classroom | \$17,385 | Medium |
| Bier Auditorium | Stage not accessible by handicapped | Build ramp or lift to stage | Assist if needed | \$7,104 | Medium |
| Ceramics | Not accessible by handicapped | Build ramp | Assist if needed | \$15,000 | Medium |
| | | | TOTAL | \$78,874.00 | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

UNIVERSITY OF MONTANA-WESTERN
 ADA SELF EVALUATION
 2005

FACILITY: Mathews Page 1 of 1

| <i>Location</i> | <i>Barrier</i> | <i>Long Term Solution</i> | <i>Interim Step</i> | <i>Cost</i> | <i>Schedule/Priority</i> |
|--|-------------------|---------------------------|---------------------|-----------------|--------------------------|
| Cafeteria Elevator | Incorrect signage | Replace signs | No interim step | \$40 | High |
| Lobby Elevator | Incorrect signage | Replace signs | No interim step | \$40 | High |
| 1 st Floor Men's Restroom | Incorrect signage | Replace signs | No interim step | \$40 | High |
| 1 st Floor Women's Restroom | Incorrect signage | Replace signs | No interim step | \$40 | High |
| | | | TOTAL | \$160.00 | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

| | | | | | |
|--|--|--|--|--|--|
| | | | | | |
|--|--|--|--|--|--|

